


COMPACT MOTOR POWER SENSOR MODEL TP-2

INDUSTRIAL APPLICATIONS:

- Pump Protection and Control
- Mixer Monitoring
- Process Feedback



MODEL TP-2

COMPACT

- 3" x 3.9" x 1.75" High (77mm x 100mm x 45mm)
- Fits in Size 1 "Buckets"
- Mounts in any direction
- DIN RAIL ADAPTOR AVAILABLE

HOOK TO

- Meters
- Data Collection Systems, MES, SCADA
- Programmable Controllers
- Recorders

4-20 MILLIAMP ANALOG OUTPUT

- Proportional to Motor Power
- Loop Powered

SIZE FOR BOTH SMALL AND LARGE MOTORS

For smaller motors




- Take more passes or turns through the window. Example: Passing the wire through twice reduces .5HP to .25HP

For larger motors



- Use with Current Transformer
- Or use UPC, Universal Power Cell

DIMENSIONS

- 3" x 3.9" x 1.75" high (77mm x 100mm x 45mm)
- Window .5" (13mm)



WHY MONITOR POWER INSTEAD OF JUST AMPS?



Also Available:
TP-2 Single Phase

TYPICAL INSTALLATION - MODEL TP-2

The TP-2 senses the electrical power input to a motor (horsepower). The Output is a 4-20 Milliamp LOOP POWERED analog signal proportional to power.

VOLTAGE

120 Volts AC are taken from two of the phases. If the motor starter already has a 120 Volt control transformer, it can be used. Otherwise, install a separate transformer. It is OK if the secondary is grounded. BE SURE TO NOTE WHICH TWO PHASES SUPPLY THE TRANSFORMER.

In a 120/208V three phase system, the 120V MUST come from a transformer connected to two of the phases. The 120V phase to ground voltage cannot be used.

CURRENT


The current signal is taken from the REMAINING phase. Pass this wire directly through the window in the TP-2.

It is VERY IMPORTANT that the current signal comes from the phase that IS NOT supplying the 120 Volt control transformer. Be extra careful when the machine has reversing starters or multi-speed windings. If a wrong phase is used the control will either:

- Work backwards
- Have reduced sensitivity

ANALOG OUTPUT

4-20MA Loop Powered.
Max. Loop voltage 28 VDC



1 & 2 = 25 HP


1 & 3 = 20 HP

24 VDC

15 HP
10 HP
5 HP
3 HP
1 HP
.5 HP

4-20MA
- +

120 VAC



SPECIFICATIONS

ACCURACY
• 2%

RESPONSE TIME
• 500 MS

TEMPERATURE
• 0-50° C

CAPACITY

Select the capacity by turning one (or two) of the Dip Switches on:

Full Scale HP

460 Volt (nominal) Primary

Switch	HP
1 & 2	25 HP
1 & 3	20 HP
1	15 HP
2	10 HP
3	5 HP
4	3 HP
5	1 HP
6	.5 HP

Multipliers

For Nominal Voltages Other than 460 Volts

Multiply 460V
full scale by:

208V = .45
230V = .5
380V = .83
415V = .9
575V = 1.25

Example: A 20 HP 230V motor should be scaled for 10 HP (20 x .5)

LARGER MOTORS: USING THE TP-2 WITH CURRENT TRANSFORMER


- Set Dip Switch for 3HP
- CT 5 Amp Secondary through hole
- Full Scale HP = (Primary Volts) (CT Primary) (0.0016)
Example: 460 Volts Primary, 100:5 Current Transformer
Full Scale HP = (460) (100) (0.0016) = 73.6HP
KW=HP x .746

Full Scale HP at 460 Volts with Current Transformer

50:5	36.8 HP	200:5	147 HP
70:5	55.2 HP	300:5	221 HP
100:5	73.6 HP	400:5	294 HP
150:5	110 HP	500:5	368 HP

REMEMBER: Put the CT on the phase that is not supplying the 120 Volt transformer.

TP-2 Wiring Diagram with External CT



Full Scale Electrical Power is calculated:
Motor Voltage x C.T. Primary Rating x 1.732 (Sq. Rt. 3) x $\frac{3.96}{5}$

Example:
Motor Voltage = 4160V CT Primary 100A
Full Scale = 4160 x 100 x 1.732 x 3.96/5 = 571 KW = 765 H.P.
Electrical Power
Output Power or Mechanical Power is calculated
Electrical Power (Either KW or HP) x Motor Efficiency